



# iPhone LCD.net

Please Note : (1) Pre-installed components(Proximity sensor bracket, earpiece speaker grill&mesh)  
 (2) Lifetime warranty  
 (3) Packing : Blister tray and cover + Inner box + Foam box + Master carton

For different grade more descriptions,please visit: [https://iphonelcd.net/our\\_grades/](https://iphonelcd.net/our_grades/)

	Quality	Unit Price >1000
<b>IP XS MAX Display Assembly</b>	OEM New	\$330.00
	OEM Refurb	\$301.00
	Original	\$291.00
<b>IP XR Display Assembly</b>	OEM Refurb	\$114.60
	Original	\$106.40
<b>IP XS Display Assembly</b>	OEM New	\$217.00
	XL-Hard OLED	\$127.00
<b>IP X Display Assembly</b>	OEM Refurb	\$191.00
	Original	\$160.70
	Soft OLED - GX	\$114.60
	Hard OLED- XL	\$96.70
	Incell- Sharp	\$78.60
	TFT- TM	\$72.90
	OEM Refurb	\$40.30
	Original	\$34.80

<b>IP 8 Plus Display Assembly</b>	Incell	\$27.90
	Premium	\$15.30
	Standard	\$14.80
	Basic	\$13.20
<b>IP 8 Display Assembly</b>	OEM Refurb	\$33.70
	Original	\$31.60
	Incell	\$21.30
	Premium	\$12.20
	Standard	\$10.50
	Basic	\$9.90
<b>IP 7 Plus Display Assembly</b>	OEM Refurb	\$37.00
	Original	\$33.20
	Incell	\$26.30
	Premium	\$15.20
	Standard	\$14.70
	Basic	\$13.20
<b>IP 7 Display Assembly</b>	OEM Refurb	\$30.40
	Original	\$28.40
	Incell	\$19.70
	Premium	\$12.00
	Standard	\$11.10
	Basic	\$9.90
<b>IP 6S Plus Display Assembly</b>	OEM Refurb	\$35.40
	Original	\$24.60
	Incell	\$27.90
	Premium	\$16.00
	Standard	\$14.50
	Basic	\$13.00
<b>IP 6S Display Assembly</b>	OEM Refurb	\$21.00
	Original	\$17.30
	Incell	\$18.00
	Premium	\$11.30
	Standard	\$10.50
	Basic	\$9.80

<b>IP 6 Plus Display Assembly</b>	OEM Refurb	\$32.10
	Original	\$30.50
	Premium	\$12.00
	Standard	\$11.50
	Basic	\$11.30
<b>IP 6 Display Assembly</b>	OEM Refurb	\$16.40
	Original	\$14.90
	Premium	\$9.30
	Standard	\$8.60
	Basic	\$7.90
<b>IP 5S Display Assembly</b>	OEM	\$21.10
	Original Refurb	\$11.50
	Standard	\$7.30
<b>IP 5C Display Assembly</b>	Original Refurb	\$11.50
	Standard	\$7.30
<b>IP 5 Display Assembly</b>	Original Refurb	\$11.50
	Standard	\$7.30
<b>IP 4S Display Assembly</b>	Original Refurb	\$7.80
	Standard	\$7.00
<b>IP 4 Display Assembly</b>	Original Refurb	\$7.80
	Standard	\$7.00